



Service Information Letter

SIL Number:	606-00004-005		
To:	Owners, Operators, and Installers of Avidyne EX5000 MFD equipped aircraft with the DFC90 autopilot		
Subject:	Updated electronic checklists for DFC90 equipped Cirrus SR2X aircraft are available via the Cirrus Tech Support website		
Purpose:	This Service Information Letter (SIL) is intended to ensure owners/operators of DFC90 equipped Cirrus SR2X aircraft are informed that updated electronic checklists for the EX5000 MFD are available		
Revision:	00	Date:	02/22/2012

Problem Description

Avidyne has worked with Cirrus Aircraft to update the electronic checklists on the EX5000 MFD to reflect DFC90 induced changes in an Avidyne Entegra cockpit for SR22, SR20, SRV aircraft. This Service Information Letter (SIL) is intended to ensure all owners and operators are aware that updated electronic checklists are available via the Cirrus Tech Support website.

Solution

For those Cirrus aircraft that are equipped with the Avidyne DFC90 autopilot and have not already upgraded the electronic checklists in the EX5000 MFD, Avidyne recommends owner/operators contact an authorized Service Center to have the checklists upgraded. The upgraded checklists are consistent with the procedures as published in the DFC90 Pilot Guide, 600-00252-000.

Cirrus Aircraft posted the updated checklists in their password protected Tech Pubs site on 31 March 2011. The password protected site can be accessed via:

http://servicecenters.cirrusdesign.com/TechPubs/mfdchecklists_avidyne.asp

Effectivity

Avidyne EX5000 P/N 700-00004-()

Accomplishment Instructions:

Not applicable.



Service Information Letter

Warranty Information:

Not Applicable.

Contact Information:

Avidyne Technical Support
1-888-723-7592 US Toll Free
1-781-402-7592 International Direct Dial
techsupport@avidyne.com
www.avidyne.com/support
Avidyne Corporation
55 Old Bedford Road
Lincoln, MA 01773